REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/10/2022	**Time:**	9:07 AM
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			**Corp ID:**	131300
Address of School Corporation:	5808 E Administration Rd				
City:	Marengo	**Zip:**	47140	**County Number:**	13
VIN:	4DRBUAAP48B499525	**License Number:**	B346Q	**Bus Number:**	3
Make of Body:	IC Corporation **Year:** 2006	**Make of Chassis:**	IC Corporation	**Year:**	2008
Bus Type:	A2	**Mileage:**	117519		
Inspection Status:	R	**Inspected By:**	Philip Lubbers	**PE:**	7703

Violations - Rejected

Inspection Code	Description
24-1-6	There are unauthorized attachments to the exterior of the bus
57-1-5	Step-well light is missing or inoperative

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**