REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	5/10/2022	Time:	12:30 PM
Name of School Co	orporation: C	RAWFORD CO. CO	OMM. SCHOOL CO	RP	Corp ID:	131300
Address of School	Corporation:	5808 E Admini	stration Rd			
City:	Marengo	Zip:	47140		County Number:	13
VIN:	4DRBUSKPXEB	405437	License Number:	7194	Bus Number:	55
Make of Body:	IC Corporation	'ear: 2014	Make of Chassis:	IC Corporation	Year:	2014
Bus Type:	С		Mileage:	133509		
Inspection Status:	R	Inspected By:	Philip Lubbers		PE:	7703

Violations - Rejected

Inspection Code	Description
17-1-1	Any dome light is inoperative
70-1-7	Any emergency window is too difficult to open
2-1-1	Required back-up lights do not function.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.