

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/11/2022	Time:	8:54 AM		
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			Corp ID:	131300		
Address of School Corporation:	5808 E Administration Rd						
City:	Marengo	Zip:	47140	County Number:	13		
VIN:	1GB6G5BG5B1162740	License Number:	2625	Bus Number:	44		
Make of Body:	GMC	Year:	2011	Make of Chassis:	Collins Bus Corporation	Year:	2011
Bus Type:	A2	Mileage:	176515				
Inspection Status:	R	Inspected By:	Philip Lubbers	PE:	7703		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-9	LED type lights have 25% to 49% pixels inoperable in any one light
17-1-1	Any dome light is inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**