## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:5/11/2022Time:9:10 AMName of School Corporation:CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:4DRBUAAP28B503197License Number:Bus Number:24Make of Body:IC Corporation Year:2008
Make of Chassis: IC Corporation Year:

Bus Type: C Mileage: 148372

Inspection Status: R Inspected By: Philip Lubbers PE: 7703

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

23-1-5 Any hanger, clamp or bracket is missing, loose or broken

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.