REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 5/11/2022 Time: 9:35 AM Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:4DRBUAFN97B369567License Number:Bus Number:32Make of Body:IC Corporation Year:2007Make of Chassis:IC Corporation Year:2007

Bus Type: C Mileage: 173633

Inspection Status: O Inspected By: Philip Lubbers PE: 7703

Violations - Rejected

<u>Inspection Code</u> 22-1-1 A dripping oil or fluid leak

70-1-7 Any emergency window is too difficult to open

Violations - Out of Service

Inspection Code Description

7-2-2 Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.