

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/11/2022	<b>Time:</b> 10:00 AM
<b>Name of School Corporation:</b> CRAWFORD CO. COMM. SCHOOL CORP	<b>Corp ID:</b> 131300	
<b>Address of School Corporation:</b> 5808 E Administration Rd		
<b>City:</b> Marengo	<b>Zip:</b> 47140	<b>County Number:</b> 13
<b>VIN:</b> 1gb6g5bg0c1110997	<b>License Number:</b> 3443	<b>Bus Number:</b> 43
<b>Make of Body:</b> Chevrolet	<b>Year:</b> 2012	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2012		
<b>Bus Type:</b> A1	<b>Mileage:</b> 120294	
<b>Inspection Status:</b> R	<b>Inspected By:</b> Philip Lubbers	<b>PE:</b> 7703

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**