# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 5/11/2022 | **Time:** | 10:13 AM |
| **Name of School Corporation:** | CRAWFORD CO. COMM. SCHOOL CORP | | | **Corp ID:** | 131300 |
| **Address of School Corporation:** | 5808 E Administration Rd | | | | |
| **City:** | Marengo | **Zip:** | 47140 | **County Number:** | 13 |
| **VIN:** | 1GDJG316881766 | **License Number:** | 24629 | **Bus Number:** | 49 |
| **Make of Body:** | GMC **Year:** 2008 | **Make of Chassis:** | GMC | **Year:** | 2008 |
| **Bus Type:** | A1 | **Mileage:** | 150803 | | |
| **Inspection Status:** | O | **Inspected By:** | Philip Lubbers | **PE:** | 7703 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 20-2-4 | Emergency door is not securely fastened to body |

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**