

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual      **Date:** 5/17/2022      **Time:** 12:12 PM  
**Name of School Corporation:** LEWIS-CASS SCHOOL CORPORATION      **Corp ID:** 90815  
**Address of School Corporation:** 6422 E SR 218  
**City:** Walton      **Zip:** 46994      **County Number:** 9  
**VIN:** 1GB6G5BL8F1145062      **License Number:** 41903      **Bus Number:** 15  
**Make of Body:** Starcraft      **Year:** 2014      **Make of Chassis:** Chevrolet      **Year:** 2015  
**Bus Type:** A2      **Mileage:** 27264  
**Inspection Status:** O      **Inspected By:** Randy McPike      **PE:** 7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.