REPORT OF SCHOOL BUS INSPECTION

Type of 9:28 Annual 5/18/2022 **Time**: Date: Inspection: AM Name of School Corporation: **CANNELTON CITY SCHOOLS** Corp ID: 626340 **Address of School Corporation:** 109 S 3rd St County City: Cannelton Zip: 47520 62 Number: License VIN: 1GBJG31K691162866 81444 **Bus Number:** 3 Number: Make of Collins Bus Year: 2009 Chevrolet Year: Make of Body: 2009 Corporation Chassis: **Bus Type:** Α1 Mileage: 69859 Inspected PE: 7703 **Inspection Status:** O Philip Lubbers By:

Violations - Rejected

Inspection Code	<u>Description</u>
43-1-8	Any required lettering is missing or faded.
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.