REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:** 5/31/2022	**Time:**	9:53 AM
Name of School Corporation:	UNION SCHOOL CORPORATION			**Corp ID:**	686795
Address of School Corporation:	8707 W US 36				
City:	Modoc	**Zip:**	47358	**County Number:**	68
VIN:	1GBJG31K591154524		**License Number:** 80600	**Bus Number:**	14
Make of Body:	Collins Bus Corporation	**Year:** 2009	**Make of Chassis:** Chevrolet	**Year:**	2009
Bus Type:	A2		**Mileage:** 82732		
Inspection Status:	O	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
29-1-5	Prohibited area sign is missing or obscured
29-1-4	Prohibited area line is missing or improper

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**