## **REPORT OF SCHOOL BUS INSPECTION**

| Type of<br>Inspection:            | Annual                   |                              |                          | Date:               | 5/27/2022                | Time:             | 12:20<br>PM |
|-----------------------------------|--------------------------|------------------------------|--------------------------|---------------------|--------------------------|-------------------|-------------|
| Name of School<br>Address of Scho | •                        |                              | /IOUNT VE<br>00 W 4th \$ |                     |                          | Corp ID:          | 656590      |
| City:                             | Mt Vernon                | Zip                          | p:                       | 47620               |                          | County<br>Number: | 65          |
| VIN:                              | 1BAKCCSA9JF34            | 0456                         |                          | License<br>Number:  | 16704                    | Bus Number:       | 63          |
| Make of Body:                     | Blue Bird<br>Corporation | <b>Year:</b> 20 <sup>-</sup> | 17                       | Make of<br>Chassis: | Blue Bird<br>Corporation | Year:             | 2018        |
| Bus Type:                         | С                        |                              |                          | Mileage:            | 61884                    |                   |             |
| Inspection<br>Status:             | A                        | lns<br>By                    | spected<br>/:            | Bradley Miller      |                          | PE:               | 7809        |

## **Violations - Rejected**

## Inspection Code Description

Violations - Out of Service

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.