# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 6/2/2022 | **Time:** | 9:50 AM |
| **Name of School Corporation:** | BLUE RIVER SERVICES | | | **Corp ID:** | 450001 |
| **Address of School Corporation:** | 3141 Progress Blvd. | | | | |
| **City:** | Corydon | **Zip:** | 47112 | **County Number:** | 31 |
| **VIN:** | 1GBJG31U351244007 | **License Number:** | 68708 | **Bus Number:** | 93 |
| **Make of Body:** | Chevrolet **Year:** 2006 | **Make of Chassis:** | Chevrolet | **Year:** | 2006 |
| **Bus Type:** | A2 | **Mileage:** | 125635 | | |
| **Inspection Status:** | O | **Inspected By:** | Troy Boyd | **PE:** | 5171 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 37-1-1 | The horn does not operate at all |
| 13-1-1 | Any clearance light is missing, cracked, faded, wrong color, or inoperative |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 8-2-1 | There is no brake certification, or the certification has expired or is not signed |

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**