REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/2/2022	**Time:**	9:50 AM
Name of School Corporation:	BLUE RIVER SERVICES			**Corp ID:**	450001
Address of School Corporation:	3141 Progress Blvd.				
City:	Corydon	**Zip:**	47112	**County Number:**	31
VIN:	1GBJG31U351244007	**License Number:**	68708	**Bus Number:**	93
Make of Body:	Chevrolet **Year:** 2006	**Make of Chassis:**	Chevrolet	**Year:**	2006
Bus Type:	A2	**Mileage:**	125635		
Inspection Status:	O	**Inspected By:**	Troy Boyd	**PE:**	5171

Violations - Rejected

Inspection Code	Description
37-1-1	The horn does not operate at all
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code	Description
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**