## REPORT OF SCHOOL BUS INSPECTION

| Type of<br>Inspection:         | Annual                   |                   | Date:              | 6/7/2022                 | Time:             | 10:44<br>AM |
|--------------------------------|--------------------------|-------------------|--------------------|--------------------------|-------------------|-------------|
| Name of School                 | •                        | FIRST STUDENT     | - INDPLS           |                          | Corp ID:          | 4981        |
| Address of School Corporation: |                          | XXX               |                    |                          |                   |             |
| City:                          | Indianapolis             | Zip:              | 46202              |                          | County<br>Number: | 49          |
| VIN:                           | 1BABLCSA0LF367029        |                   | License<br>Number: |                          | Bus Number:       | 109         |
| Make of Body:                  | Blue Bird<br>Corporation | <b>Year:</b> 2019 | Make of Chassis:   | Blue Bird<br>Corporation | Year:             | 2020        |
| Bus Type:                      | D                        |                   | Mileage:           | 19152                    |                   |             |
| Inspection<br>Status:          | 0                        | Inspected<br>By:  | Nick Cox           |                          | PE:               | 8795        |

## Violations - Rejected

# <u>Inspection Code</u> <u>Description</u>

16-1-1 There are any leaks from the differential, pinion seal, hubs or wheel seals

#### **Violations - Out of Service**

| Inspection<br>Code | <u>Description</u>   |
|--------------------|--|
| 34-2-2             | Both lamps are inoperative on high beam  |
| 7-2-8              | There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely |

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.