

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/8/2022	Time: 9:30 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP.	Corp ID: 80750	
Address of School Corporation: 2 S 3rd St.		
City: Flora	Zip: 46929	County Number: 8
VIN: 4DRBUAAP08B498839	License Number: 9113	Bus Number: 19
Make of Body: IC Corporation	Year: 2008	Make of Chassis: IC Corporation
Year: 2008	Mileage: 182623	PE: 7421
Bus Type: C	Inspected By: Nate King	
Inspection Status: O		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.