REPORT OF SCHOOL BUS INSPECTION

Time: 9:46 AM **Type of Inspection:** Annual Date: 6/8/2022

CARROLL CONS. SCHOOL CORP. Name of School Corporation:

Corp ID: 80750

Address of School Corporation: 2 S 3rd St.

City: Flora Zip: 46929 **County Number: 8** VIN: 4DRBUC8P5HB722463 **Bus Number:** License Number: 12553 22 Make of Body: Make of Chassis: IC Corporation Year: 2017 IC Corporation Year: 2017

Bus Type: С Mileage: 54710

PE: 7421 **Inspection Status:** R Inspected By: Nate King

Violations - Rejected

Description Inspection Code

17-1-1 Any dome light is inoperative

26-1-4 Not securely mounted

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.