

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/8/2022	Time: 1:10 PM	
Name of School Corporation: CARROLL CONS. SCHOOL CORP.	Corp ID: 80750		
Address of School Corporation: 2 S 3rd St.			
City: Flora	Zip: 46929	County Number: 8	
VIN: 4DRBUC8P8GB121465	License Number: 10247	Bus Number: 14	
Make of Body: IC Corporation	Year: 2016	Make of Chassis: IC Corporation	Year: 2016
Bus Type: C	Mileage: 68950		
Inspection Status: O	Inspected By: Nate King	PE: 7421	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
65-2-5	LED lights have 50% or more of the pixels inoperable

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.