

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 6/9/2022 **Time:** 10:53 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP. **Corp ID:** 80750
Address of School Corporation: 2 S 3rd St.
City: Flora **Zip:** 46929 **County Number:** 8
VIN: 1GB3G2BL6D1167608 **License Number:** 19265 **Bus Number:** 3sb
Make of Body: Chevrolet **Year:** 2013 **Make of Chassis:** Chevrolet **Year:** 2013
Bus Type: A1 **Mileage:** 124034
Inspection Status: O **Inspected By:** Nate King **PE:** 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (½) inch in diameter.

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.