

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 6/9/2022 Time: 10:53 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP. Corp ID: 80750
Address of School Corporation: 2 S 3rd St.
City: Flora Zip: 46929 County Number: 8
VIN: 1GB3G2BL6D1167608 License Number: 19265 Bus Number: 3sb
Make of Body: Chevrolet Year: 2013 Make of Chassis: Chevrolet Year: 2013
Bus Type: A1 Mileage: 124034
Inspection Status: O Inspected By: Nate King PE: 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (½) inch in diameter.

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.