REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:6/15/2022Time:9:17 AMName of School Corporation:SOUTHWEST PARKE COMM SCH CORPCorp ID:616260

Address of School Corporation: RR 1

City:MontezumaZip:47862County Number:61VIN:4DRBUC8N0GB207772License Number:Bus Number:8Make of Body:IC Corporation Year:2015Make of Chassis:IC Corporation Year:2016

Bus Type: C Mileage: 42158

Inspection Status: O Inspected By: Byron Goodman PE: 7008

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.