

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 6/15/2022 **Time:** 9:17 AM
Name of School Corporation: SOUTHWEST PARKE COMM SCH CORP **Corp ID:** 616260
Address of School Corporation: RR 1
City: Montezuma **Zip:** 47862 **County Number:** 61
VIN: 4DRBUC8N0GB207772 **License Number:** B987K **Bus Number:** 8
Make of Body: IC Corporation **Year:** 2015 **Make of Chassis:** IC Corporation **Year:** 2016
Bus Type: C **Mileage:** 42158
Inspection Status: O **Inspected By:** Byron Goodman **PE:** 7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.