REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/22/2022	**Time:**	9:37 AM
Name of School Corporation:	EASTERN HANCOCK CSC			**Corp ID:**	303145
Address of School Corporation:	10370 E 250 N				
City:	Charlottesville	**Zip:**	46117	**County Number:**	30
VIN:	1BAKGCPA2AF274314	**License Number:**	72243	**Bus Number:**	26
Make of Body:	Blue Bird Corporation **Year:** 2010	**Make of Chassis:**	Blue Bird Corporation	**Year:**	2010
Bus Type:	C	**Mileage:**	101064		
Inspection Status:	O	**Inspected By:**	Joel Flores	**PE:**	7415

Violations - Rejected

Inspection Code	Description
50-1-2	The seat belt cutter is not secured using a positive fastening method.
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
29-1-7	See Notes: Any defect inspector deems a violation not listed
67-1-5	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
59-2-3	Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.