## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:6/22/2022Time:9:07 AMName of School Corporation:SOUTH HARRISON COMM. SCH. CORPCorp ID:313190

Address of School Corporation: 315 S Harrison Dr

City:CorydonZip:47112County Number:31VIN:4UZAAXCT24CL83486License Number:Bras Number:1Make of Body:Freightliner Year:2004
Make of Chassis: Freightliner Year:

Bus Type: C Mileage: 170915

Inspection Status: O Inspected By: Troy Boyd PE: 5171

## Violations - Rejected

Inspection Code	<u>Description</u>
24-1-1	The bus body has rust or rusted through areas which may weaken the body
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
46-1-1	Any seat is loose from the floor or seat rail

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.