

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	6/29/2022	Time:	12:53 PM
Name of School Corporation:	HUMAN SERVICES INC. HEAD START	Corp ID:	03003Z		
Address of School Corporation:	PO Box 119				
City:	Clifford	Zip:	47203	County Number:	3
VIN:	1GBJG31K691144861	License Number:	32127	Bus Number:	102
Make of Body:	Blue Bird Corporation	Year:	2010	Make of Chassis:	GMC
Year:	2009	Mileage:	106570		
Bus Type:	A1	Inspected By:	Seth Davidson	PE:	8101
Inspection Status:	O				

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-5	See Notes: Any defect inspector deems a violation not listed
64-1-4	Any front turn signal does not function properly

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.