## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:6/30/2022Time:9:34 AMName of School Corporation:CULVER COMMUNITY SCHOOLS CORP.Corp ID:505455

Address of School Corporation: PO Box 231

City:CulverZip:46511County Number:50VIN:4DRBUC8P0KB600228License Number:22363Bus Number:29Make of Body:IC Corporation Year:2018Make of Chassis:IC Corporation Year:2018

Bus Type: C Mileage: 33237

Inspection Status: A Inspected By: Travis Harrold PE: 8022

Violations - Rejected

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.