

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/6/2022	Time:	10:51 AM
Name of School Corporation:	SHERIDAN COMMUNITY SCHOOLS			Corp ID:	293055
Address of School Corporation:	24795 Hinsley Rd				
City:	Sheridan	Zip:	46069	County Number:	29
VIN:	1T7YR4E2XC1144005	License Number:	7629	Bus Number:	10
Make of Body:	Thomas Built Buses, Inc.	Year:	2012	Make of Chassis:	Freightliner
Bus Type:	D	Mileage:	94648	Year:	2012
Inspection Status:	O	Inspected By:	Brandon Steffee	PE:	8247

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-2	Any shock absorber is leaking fluid
52-1-1	There are any loose, broken, or missing mountings
3-1-8	Battery compartment floor is weakened from rust

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.