REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:** 7/6/2022	**Time:**	10:51 AM
Name of School Corporation:	SHERIDAN COMMUNITY SCHOOLS			**Corp ID:**	293055
Address of School Corporation:	24795 Hinsley Rd				
City:	Sheridan	**Zip:**	46069	**County Number:**	29
VIN:	1T7YR4E2XC1144005		**License Number:** 7629	**Bus Number:**	10
Make of Body:	Thomas Built Buses, Inc. **Year:** 2012		**Make of Chassis:** Freightliner	**Year:**	2012
Bus Type:	D		**Mileage:** 94648		
Inspection Status:	O	**Inspected By:**	Brandon Steffee	**PE:**	8247

Violations - Rejected

Inspection Code	Description
52-1-2	Any shock absorber is leaking fluid
52-1-1	There are any loose, broken, or missing mountings
3-1-8	Battery compartment floor is weakened from rust

Violations - Out of Service

Inspection Code	Description
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.