## REPORT OF SCHOOL BUS INSPECTION

Time: **Type of Inspection:** Annual Date: 7/11/2022 9:05 AM Corp ID: 454615

LAKE CENTRAL SCHOOL CORP. Name of School Corporation:

**Address of School Corporation:** 8855 Wicker Ave City: St John Zip: 46373 **County Number: 45** VIN: 4DRBUSKN4BB338117 **Bus Number:** 71 License Number: 74946 Make of Body: Make of Chassis: IC Corporation Year: 2011 IC Corporation Year: 2010

**Bus Type:** С Mileage: 149110

**Inspection Status:** R PE: 7029 **Inspected By:** Nathan Sherer

## **Violations - Rejected**

<u>Inspection</u> **Description** Code

There is an air leak from any hose, line, tank, bag, or other component of an air 61-1-4

suspension system

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.