REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection		**Date:** 7/18/2022	**Time:**	9:04 AM
Name of School Corporation:	UNION SCHOOL CORPORATION			**Corp ID:**	686795
Address of School Corporation:	8707 W US 36				
City:	Modoc	**Zip:**	47358	**County Number:**	68
VIN:	1GBJG31K591154524		**License Number:** 80600	**Bus Number:**	14
Make of Body:	Collins Bus Corporation	**Year:** 2009	**Make of Chassis:** Chevrolet	**Year:**	2009
Bus Type:	A2		**Mileage:** 84112		
Inspection Status:	R	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**