

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/18/2022	Time:	9:55 AM
Name of School Corporation:	UNION SCHOOL CORPORATION	Corp ID:	686795		
Address of School Corporation:	8707 W US 36				
City:	Modoc	Zip:	47358	County Number:	68
VIN:	1GBJG31UX61235063	License Number:	71513	Bus Number:	12
Make of Body:	U.S. Bus Corporation	Year:	2006	Make of Chassis:	Chevrolet
Bus Type:	A2	Mileage:	92027	Year:	2006
Inspection Status:	R	Inspected By:	Steve Spallinger	PE:	6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.