

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	7/19/2022	Time:	9:37 AM		
Name of School Corporation:	EDINBURGH COMM. SCHOOL CORP.			Corp ID:	414215		
Address of School Corporation:	202 S Keeley St						
City:	Edinburg	Zip:	46124	County Number:	41		
VIN:	4DRBVAAR66A211747		License Number:	4861	Bus Number:	5	
Make of Body:	IC Corporation	Year:	2005	Make of Chassis:	IC Corporation	Year:	2006
Bus Type:	D			Mileage:	128199		
Inspection Status:	O	Inspected By:	Joel Flores	PE:	7415		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.