

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|-----------------------------|------------------------|-------------|-------------------------|----------------|
| Type of Inspection: | Re-Inspection | Date: | 7/19/2022 | Time: | 9:03 AM |
| Name of School Corporation: | ILLINOIS CENTRAL SCHOOL BUS | Corp ID: | 45015Z | | |
| Address of School Corporation: | 801 E Main | | | | |
| City: | Griffith | Zip: | 46319 | County Number: | 45 |
| VIN: | 4DRBUAAP3EB416548 | License Number: | B303T | Bus Number: | 4849 |
| Make of Body: | IC Corporation | Year: | 2012 | Make of Chassis: | IC Corporation |
| Year: | | Year: | | Year: | 2014 |
| Bus Type: | C | Mileage: | 89038 | | |
| Inspection Status: | O | Inspected By: | Tim Grayson | PE: | 7558 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 59-1-4 | LED type lights have 25% to 49% pixels inoperable in any one light. (NOTE: one letter in the word "STOP" equals one light) |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 8-2-5 | There is brake fluid leaking at any point |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.