

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	7/26/2022	Time:	9:20 AM		
Name of School Corporation:	SOUTH DEARBORN COMM. SCH. CORP			Corp ID:	151600		
Address of School Corporation:	6109 Squire Place						
City:	Aurora	Zip:	47001	County Number:	15		
VIN:	1HVBBAFP43H560915		License Number:	BL37L	Bus Number:	3A	
Make of Body:	Blue Bird Corporation	Year:	2002	Make of Chassis:	IC Corporation	Year:	2003
Bus Type:	C			Mileage:	87966		
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-5	Any paint is badly faded or peeling
41-1-8	The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.