# **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Re-Inspection			Date:	7/26/2022	Time:	9:20 AM
Name of School Corporation: Address of School Corporation:		SOU	SOUTH DEARBORN COMM. SCH. CORP 6109 Squire Place			Corp ID:	151600
City:	Aurora		Zip:	47001		County Number:	15
VIN:	N: 1HVBBABP43H560915			License Number:	BL37L	Bus Number:	3A
Make of Body:	Blue Bird Corporation	Year	2002	Make of Chassis:	IC Corporation	Year:	2003
Bus Type:	С			Mileage:	87966		
Inspection Status	s: 0		Inspected By:	Chris Clark		PE:	6665

## **Violations - Rejected**

Inspection <u>Code</u>	<u>Description</u>
24-1-5	Any paint is badly faded or peeling
41-1-8	The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device.

## Violations - Out of Service

### Inspection Code

**Description** 20-2-1 Is no audible signal when the emergency door is open and ignition switch is on

### **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.