

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 8/10/2022 **Time:** 9:33 AM
Name of School Corporation: JENNINGS COUNTY SCHOOL CORP. **Corp ID:** 404015
Address of School Corporation: 34 Main St
City: North Vernon **Zip:** 47265 **County Number:** 40
VIN: 4UZAAXCS94CM20590 **License Number:** B169L **Bus Number:** 403
Make of Body: Freightliner **Year:** 2003 **Make of Chassis:** Freightliner **Year:** 2004
Bus Type: B **Mileage:** 193001
Inspection Status: R **Inspected By:** Chris Clark **PE:** 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
66-1-1	Required warning devices are not present

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.