REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	8/10/2022	**Time:**	9:33 AM
Name of School Corporation:	JENNINGS COUNTY SCHOOL CORP.			**Corp ID:**	404015
Address of School Corporation:	34 Main St				
City:	North Vernon	**Zip:**	47265	**County Number:**	40
VIN:	4UZAAXCS94CM20590	**License Number:**	B169L	**Bus Number:**	403
Make of Body:	Freightliner **Year:** 2003	**Make of Chassis:**	Freightliner	**Year:**	2004
Bus Type:	B	**Mileage:**	193001		
Inspection Status:	R	**Inspected By:**	Chris Clark	**PE:**	6665

Violations - Rejected

Inspection Code	Description
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
66-1-1	Required warning devices are not present

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.