

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 8/15/2022 Time: 9:23 AM  
Name of School Corporation: NORTH WEST HENDRICKS SCHOOLS Corp ID: 323295  
Address of School Corporation: PO Box 70  
City: Lizton Zip: 46149 County Number: 32  
VIN: 1GB3GRBG4G1185895 License Number: 36988 Bus Number: 161  
Make of Body: Chevrolet Year: 2016 Make of Chassis: Chevrolet Year: 2016  
Bus Type: A1 Mileage: 86440  
Inspection Status: R Inspected By: Nick Cox PE: 8795

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.