

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection Date: 8/15/2022 Time: 9:32 AM  
Name of School Corporation: NORTH WEST HENDRICKS SCHOOLS Corp ID: 323295  
Address of School Corporation: PO Box 70  
City: Lizton Zip: 46149 County Number: 32  
VIN: 1GB3GRBG6G1322464 License Number: NWH162 Bus Number: 162  
Make of Body: Chevrolet Year: 2016 Make of Chassis: Chevrolet Year: 2016  
Bus Type: A1 Mileage: 68452  
Inspection Status: O Inspected By: Nick Cox PE: 8795

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
51-2-1	The service door does not open or close properly

## Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.