

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 8/15/2022 **Time:** 9:32 AM
Name of School Corporation: NORTH WEST HENDRICKS SCHOOLS **Corp ID:** 323295
Address of School Corporation: PO Box 70
City: Lizton **Zip:** 46149 **County Number:** 32
VIN: 1GB3GRBG6G1322464 **License Number:** NWH162 **Bus Number:** 162
Make of Body: Chevrolet **Year:** 2016 **Make of Chassis:** Chevrolet **Year:** 2016
Bus Type: A1 **Mileage:** 68452
Inspection Status: O **Inspected By:** Nick Cox **PE:** 8795

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
51-2-1	The service door does not open or close properly

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.