REPORT OF SCHOOL BUS INSPECTION

Type of Semi-Annual Date: 8/19/2022 Time: 10:00 AM

Name of School Corporation: BLACKFORD COUNTY SCHOOLS Corp ID: 50515

Address of School Corporation: 668 W CR 200S

City:Hartford CityZip:47348County Number: 5VIN:4DRBUAAN6BB327325License Number: 74622Bus Number: 110

Make of Body: IC Corporation Year: 2010 Make of Chassis: IC Corporation Year: 2011

Bus Type: C Mileage: 104713

Inspection Status: R Inspected By: Steve Spallinger PE: 6921

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

35-1-1 A heater motor is not operating properly

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.