REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	8/10/2022	**Time:**	2:03 PM
Name of School Corporation:	CLAY COMMUNITY SCHOOLS			**Corp ID:**	111125
Address of School Corporation:	PO Box 169				
City:	Knightsville	**Zip:**	47857	**County Number:**	11
VIN:	1BAKJCSA6MF374932	**License Number:**	24417	**Bus Number:**	62
Make of Body:	Blue Bird Corporation **Year:** 2020	**Make of Chassis:**	Blue Bird Corporation	**Year:**	2021
Bus Type:	C	**Mileage:**	14453		
Inspection Status:	O	**Inspected By:**	Byron Goodman	**PE:**	7008

Violations - Rejected

Inspection Code	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.