

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 8/25/2022 **Time:** 10:28 AM
Name of School Corporation: JENNINGS COUNTY SCHOOL CORP. **Corp ID:** 404015
Address of School Corporation: 34 Main St
City: North Vernon **Zip:** 47265 **County Number:** 40
VIN: 4DRBWAARX7A402019 **License Number:** 21541 **Bus Number:** 303
Make of Body: AmTran **Year:** 2006 **Make of Chassis:** AmTran **Year:** 2007
Bus Type: D **Mileage:** 116012
Inspection Status: R **Inspected By:** Chris Clark **PE:** 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
69-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.