

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	8/29/2022	<b>Time:</b>	12:21 PM
<b>Name of School Corporation:</b>	AUXILIO SERVICES (MUNCIE)			<b>Corp ID:</b>	251807
<b>Address of School Corporation:</b>	11260 Cornell Park Dr Suite 700				
<b>City:</b>	Cincinnati	<b>Zip:</b>	45242	<b>County Number:</b>	18
<b>VIN:</b>	4DRBUC8N7JB043637	<b>License Number:</b>		<b>Bus Number:</b>	M-31
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2017	<b>Make of Chassis:</b>	IC Corporation
		<b>Year:</b>		<b>Year:</b>	0
<b>Bus Type:</b>	C	<b>Mileage:</b>	57284		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Steve Spallinger	<b>PE:</b>	6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
7-1-3	Air leak at proper connection
29-1-4	Prohibited area line is missing or improper
29-1-5	Prohibited area sign is missing or obscured

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.