## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Re-InspectionDate:9/1/2022Time:9:51 AM

Name of School Corporation: DUGGER UNION COMMUNITY SCHOOLS Corp ID: 9950

Address of School Corporation: 7356 E. Co. Rd. 50 S.

City:DuggerZip:47848County Number:77VIN:4DRBUC8N1HB373395License Number:13048Bus Number:1Make of Body:IC Corporation Year:2017

Bus Type: C Mileage: 87549

Inspection Status: R Inspected By: Byron Goodman PE: 7008

## **Violations - Rejected**

<u>Inspection Code</u> <u>Description</u>

41-1-4 There is debris in the bus. (needs cleaned/includes dirt)

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.