REPORT OF SCHOOL BUS INSPECTION

Type of Semi-Annual 9/13/2022 **Time**: Date: 9:24 AM Inspection: Name of School Corporation: SOUTHEAST DUBOIS CO. SCH. CORP. 192100 Corp ID: **Address of School Corporation:** 432 E 15th St County City: Ferdinand Zip: 47532 19 Number: License VIN: 1GBL7T1D2XJ105286 B833H **Bus Number:** 4 Number: Make of Blue Bird Chevrolet Year: **Year:** 1999 Make of Body: 1999 Corporation Chassis: **Bus Type:** С Mileage: 136429 Inspected PE: 7703 Inspection Status: R Philip Lubbers By:

Violations - Rejected

Inspection Code

49-1-4 Any reflector is missing, cracked, faded, or the wrong color.

Description

The area around any warning light is not painted black

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.