REPORT OF SCHOOL BUS INSPECTION

Type of 10:20 Semi-Annual Date: 9/13/2022 **Time**: Inspection: ΑM Name of School Corporation: SOUTHEAST DUBOIS CO. SCH. CORP 192100 Corp ID: **Address of School Corporation:** 432 E 15th St County City: Ferdinand Zip: 47532 19 Number: License VIN: 1GBL7T1C51J509035 B830H **Bus Number:** Number: Make of Blue Bird Chevrolet Year: Year: 2001 Make of Body: 2001 Corporation Chassis: **Bus Type:** С Mileage: 206083 Inspected PE: 7703 **Inspection Status:** O Philip Lubbers By:

Violations - Rejected

Inspection Code	<u>Description</u>
65-1-2	The area around any warning light is not painted black
24-1-3	The bus is not painted National School Bus Yellow

Violations - Out of Service

Inspection Code	<u>Description</u>
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.