

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 9/13/2022 **Time:** 10:34 AM
Name of School Corporation: SOUTHEAST DUBOIS CO. SCH. CORP **Corp ID:** 192100
Address of School Corporation: 432 E 15th St
City: Ferdinand **Zip:** 47532 **County Number:** 19
VIN: 4UZAAXCT24CL83651 **License Number:** B832H **Bus Number:** 6
Make of Body: Freightliner **Year:** 2002 **Make of Chassis:** Freightliner **Year:** 2004
Bus Type: C **Mileage:** 227527
Inspection Status: R **Inspected By:** Philip Lubbers **PE:** 7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.