

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 9/13/2022      **Time:** 10:35 AM  
**Name of School Corporation:** SOUTHEAST DUBOIS CO. SCH. CORP      **Corp ID:** 192100  
**Address of School Corporation:** 432 E 15th St  
**City:** Ferdinand      **Zip:** 47532      **County Number:** 19  
**VIN:** 4UZAAXCT24CL83651      **License Number:** B832H      **Bus Number:** 6  
**Make of Body:** Freightliner      **Year:** 2002      **Make of Chassis:** Freightliner      **Year:** 2004  
**Bus Type:** C      **Mileage:** 227527  
**Inspection Status:** R      **Inspected By:** Philip Lubbers      **PE:** 7703

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**