

REPORT OF SCHOOL BUS INSPECTION

| | | |
|--|----------------------------------|--|
| Type of Inspection: Semi-Annual | Date: 9/13/2022 | Time: 9:37 AM |
| Name of School Corporation: FRANKLIN COMM. SCHOOL CORP. | Corp ID: 414225 | |
| Address of School Corporation: 750 E SR 44 | | |
| City: Franklin | Zip: 46131 | County Number: 41 |
| VIN: 4DRBWAAR78A498791 | License Number: 7892 | Bus Number: 103 |
| Make of Body: IC Corporation | Year: 2006 | Make of Chassis: IC Corporation |
| Year: 2008 | Mileage: 101720 | PE: 7415 |
| Bus Type: D | Inspected By: Joel Flores | |
| Inspection Status: O | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 30-1-3 | See Notes: Any defect inspector deems a violation not listed |
| 20-1-8 | If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly |
| 24-1-7 | See Notes: Any defect inspector deems a violation not listed |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 32-2-1 | There is fuel leaking from any point on in the fuel system |

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.