

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                         |                        |               |                         |                       |
|---------------------------------------|-------------------------|------------------------|---------------|-------------------------|-----------------------|
| <b>Type of Inspection:</b>            | Annual                  | <b>Date:</b>           | 9/13/2022     | <b>Time:</b>            | 11:24 AM              |
| <b>Name of School Corporation:</b>    | AREA 30 CAREER CENTER   | <b>Corp ID:</b>        | 676000        |                         |                       |
| <b>Address of School Corporation:</b> | 1 N Calbert Way Suite A |                        |               |                         |                       |
| <b>City:</b>                          | Greencastle             | <b>Zip:</b>            | 46135         | <b>County Number:</b>   | 67                    |
| <b>VIN:</b>                           | 1BAAGCPA34F211271       | <b>License Number:</b> | 19570         | <b>Bus Number:</b>      | 4                     |
| <b>Make of Body:</b>                  | Blue Bird Corporation   | <b>Year:</b>           | 2002          | <b>Make of Chassis:</b> | Blue Bird Corporation |
| <b>Bus Type:</b>                      | D                       | <b>Mileage:</b>        | 27421         | <b>Year:</b>            | 2004                  |
| <b>Inspection Status:</b>             | O                       | <b>Inspected By:</b>   | Byron Goodman | <b>PE:</b>              | 7008                  |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 24-1-2                 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**